LMA District Cover Sheet

Spring 2009 Levee Inspection Results

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)					
* Overall LMA Rating (Fall Only)									
	** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.								
* SPRING INSPECTIONS: Overall maintenance deficiencies are rated		nined for the spring ins		ual maintenance					
	The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.								
Comments									

Unit Cover Sheet

Spring 2009 Levee Inspection Results

Knights Landing Ridge Drainage District

Waterway Bank Unit Miles									
	Unit No. 01 Knights L	•		Right	6.40				
	Spring	Summer	(September - November)		Winter				
	(March - May)	(June - August)	Fall		ber - February)				
Unit Maintenance Rating (Fall Only)									
Date of Inspection	4/9/2009 - 4/9/2009								
DWR Inspector	John Williamson								
Accompanied By									
project components conditions other that deficiencies identified. During the current with project components maintenance and the following changes in the coordinates, location. Comments One of the boxes above is information must also be so DWR with any additional states.	vinter (or summer) inspection projection in the results of our normal mained in the enclosed report. Vinter (or summer) inspection projection in the enclosed report. Vinter (or summer) inspection projection in the attached Leve experience corrections we have made to a flood project conditions. Section below or on additional sheen (Land Side, Water Side, or Constitution) in the condition of the condition in t	e Inspection Report by intenance and the correletion, my staff or I have a Inspection Report by maintenance deficience (s), identify change corown), Item identification laintaining Agency (LM/eet should be signed and mer Inspection) or Marchands (1998).	Mile. We have found no charactions we have made to main extremely a inspected the levee and ass Mile. In addition to the results ties identified in the report, we of condition by: Start to End Lan, and description of the curred. A). If the second box is checked dated by the LMA Represench 31 (Winter Inspection). Ple	ociated flos of our note have four evee Mile ent conditional ed, additionative an	ood project ood ormal ind the or GPS ion).				
your records. Please mail	3	WR Summer/Winter In 310 El Camino Avenue acramento, CA 95821-	, Room LL-30						

X

Signature of LMA Representative

Date

Levee Inspection Report By Mile - Spring 2009

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Knights Landing Ridge Cut	Right	6.40	04/09/2009 04/09/2009	John Williamson

LMR	Levee	Mile			Loca	Ra		GPS Latitude/Longitude	2 8
Line	Start	End	Category	Item	Location *	Rating	Action/Comment	Start End	Issue
1	0.00	0.26	Boat Survey	Boat Survey Erosion	LS	М	Inspector Comments: tension cracks, slumping	38.722262 ° 38.718938 ° -121.666350 ° -121.663858 °	933
2	0.02	6.13	Earthen Levee	Vegetation	LS	М	Control annual grass and weeds on the levee slopes and easements.	38.719224 ° 38.789623 ° -121.664195 ° -121.722911 °	935
3	0.02	6.41	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.719229 ° 38.792388 ° -121.664197 ° -121.726552 °	934
4	1.16	1.16	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.730265 ° 38.730265 ° -121.678982 ° -121.678982 °	3
5	1.36	1.36	Earthen Levee	Trim / Thin Trees	WS	M	Trim and thin trees to allow visibility of the ground and room to flood fight.	38.732418 ° 38.732418 ° -121.681292 ° -121.681292 °	4
6	1.47	1.47	Earthen Levee	Animal Control	LS	М	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: bait station are in place	38.733706 ° 38.733706 ° -121.682455 ° -121.682455 °	8
7	1.69	1.69	Earthen Levee	Animal Control	LS	М	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: bait stations are in place	38.736200 ° 38.736200 ° -121.684970 ° -121.684970 °	9
8	2.46	2.46	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: bait stations are in place	38.745451° 38.745451° -121.692931°-121.692931°	10
9	2.71	2.71	Earthen Levee	Encroachments	LS	М	Garbage	38.748521 ° 38.748521 ° Y -121.695002 ° -121.695002 °	 11
10	4.39	4.39	Earthen Levee	Animal Control	LS	М	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: bait stations are in place	38.770340 ° 38.770340 ° -121.703308 ° -121.703308 °	12
11	6.17	6.41	Earthen Levee	Encroachments	LS	РО	Equipment	38.790007 ° 38.792433 ° -121.723308 ° -121.726463 °	7

Levee Inspection Report By Mile - Spring 2009

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector	
Unit No. 01 Knights Landing Ridge Cut	Right	6.40	04/09/2009 04/09/2009	John Williamson	

Levee Mile Report Line	9
Start Levee Mile	2.71
End Levee Mile	2.71
Location	Land Side
Category	Earthen Levee
Item	Encroachments
pile along road 17	



Unit Cover Sheet

Spring 2009 Levee Inspection Results

Knights Landing Ridge Drainage District

	Water	,		Bank	Unit Miles		
	Unit No. 02 Knights I	_anding Ridge Cut		Left	6.20		
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - Feb			
Unit Maintenance Rating (Fall Only)							
Date of Inspection	4/9/2009 - 4/9/2009						
DWR Inspector	John Williamson						
Accompanied By							
Check one:							
 During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report. During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions. (In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition). 							
information must also be s	3	eet should be signed ar	nd dated by the LMA Represer ch 31 (Winter Inspection). Plea aspection Reports e, Room LL-30	ntative an	d returned to		

X

Signature of LMA Representative

Date

Levee Inspection Report By Mile - Spring 2009

Knights Landing Ridge Drainage District

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Knights Landing Ridge Cut	Left	6.20	04/09/2009 04/09/2009	John Williamson

LMR Line	Levee	Mile	Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude Start End	Issue
1	0.02	6.04	Earthen Levee	Vegetation	LS	М	Control annual grass and weeds on the levee slopes and easements.	38.724504 ° 38.792649 ° -121.665486 ° -121.724033 °	938
2	0.02	6.04	Earthen Levee	Vegetation	WS	M	Control annual grass and weeds on the levee slopes and easements.	38.724504 ° 38.792647 ° -121.665490 ° -121.724034 °	939
3	0.69	0.75	Earthen Levee	Vegetation	WS	M	Remove the wild growth other than native grasses from the levee slopes.	38.730015 ° 38.730602 ° -121.675337 ° -121.676190 °	5
4	0.95	0.95	Earthen Levee	Vegetation	ws	M	Remove the wild growth other than native grasses from the levee slopes.	38.732577 ° 38.732577 ° -121.678772 ° -121.678772 °	4
5	1.26	1.26	Earthen Levee	Animal Control	LS	M	Exterminate rodents and backfill and compact or grout burrows. Inspector Comments: bait stations are in place	38.736183 ° 38.736183 ° -121.682145 ° -121.682145 °	7
6	1.27	1.51	Earthen Levee	Crown Surface / Depressions / Rutting	CR	M	Keep the crown roadway free of vegetation.	38.736310 ° 38.739139 ° -121.682349 ° -121.684904 °	942
7	2.29	2.29	Earthen Levee	Encroachments	LS	М	Garbage	38.748449 ° 38.748449 ° -121.692680 ° -121.692680 °	Y 941
8	2.74	2.96	Boat Survey	Boat Survey Erosion	LS	M	Inspector Comments: slumping	38.757942 ° 38.754902 ° -121.692963 ° -121.692565 °	934
9	3.01	3.08	Boat Survey	Boat Survey Erosion	LS	M	Inspector Comments: piping holes, tension cracks, slumping	38.759468 ° 38.758623 ° -121.693963 ° -121.693285 °	935
10	3.35	3.97	Earthen Levee	Encroachments	LS	РО	Agricultural Ditch	38.762362 ° 38.770357 ° -121.697247 ° -121.701281 °	940
11	4.01	4.09	Boat Survey	Boat Survey Erosion	LS	М	Inspector Comments: tension cracks, slumping	38.771932 ° 38.770901 ° -121.701728 ° -121.701391 °	936
12	4.39	6.03	Boat Survey	Boat Survey Erosion	LS	М	Inspector Comments: tension cracks, slumping	38.792562 ° 38.775824 ° -121.724002 ° -121.703773 °	937
13	6.05	6.12	Earthen Levee	Encroachments	LS	CO	Crops Inspector Comments: no access strawberies are being grown landside levee slope and crown	38.792735 ° 38.792735 ° -121.724092 ° -121.724092 °	1

* Location
LS: Land Side
WS: Water Side
CR: Crown

A : Acceptable
M : Minimally Acceptable
U : Unacceptable

PO : Partially Obstructing CO : Completely Obstructing N : Not Inspected

C : Corrected

Levee Inspection Report By Mile - Spring 2009

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Knights Landing Ridge Cut	Left	6.20	04/09/2009 04/09/2009	John Williamson

7
2.29
2.29
Land Side
Earthen Levee
Encroachments

